



BMW 316D: 1HYG827

Vinnnumber:	WBA3K91040F936613	Versionname:	DIESEL
First Registrationdate:	29/10/2014	Fiscalpower:	
Expertise Mileage:	86829	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2612
Maintenance:	29000KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Type of Tow bar	Tow bar removable
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Toyo: 6 mm	Fr.R.	Toyo: 5 mm
	Re.L.	Toyo: 6 mm	Re.R.	Toyo: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1039,90
-------------------	----------------

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------



Alloy rim F R, Scratch(es), Acceptable

0,00



Bonnet, Scratch(es), 67 - Polish

0,00



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Bumper R, Scratch(es), Acceptable

0,00



Tailgate, Scratch(es), 67 - Polish

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door panel F L, Scratch(es), Acceptable

0,00



Gear shift lever knob, Worn, Acceptable

0,00



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Rear wiper blade, Incomplete, Acceptable

0,00



Seat cover F L, Worn, Acceptable

0,00



Door panel F R, Scratch(es), Acceptable

0,00



Wing R R, Scratch(es), Acceptable

0,00



Door F L, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper F, Scratch(es), Acceptable

0,00



Door R R, Scratch(es), Acceptable

0,00



Ignition key, Worn, Acceptable

0,00



Rearlight L, Scratch(es), 67 - Polish

0,00

