



| | | | |
|------------------------------------|--------------------------|--------------|-------------------------------|
| AUDI A6: 1GQI758 | | | |
| Vinnumber: | WAUZZZ4G7EN129580 | Versionname: | A6 AVANT Multitr.163PK |
| First Registrationdate: | 1/04/2014 | Fiscalpower: | |
| Expertise Mileage: | 127009 | Power Kw: | 120 |
| Bodytype: | Break | Body color: | Brown |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1512 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Options | | | |
| Radio CD | | Central consol F | |
| GPS storage | HD | Luggage cover | |
| GPS storage | | Front parking sensors | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | Type of Tow bar | No Tow bar |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Seats F heated | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

| | | | |
|-------------------------------------|-----------|---------------------|------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| | | | | |
|-----------------------|----------------------------------|---------------------|-------|---------------------|
| Degree of wear | | | | |
| | 225/55/17/97 W LightMetal | | | |
| Summer tyres: | Fr.L. | Kleber: 4 mm | Fr.R. | Kleber: 4 mm |
| | Re.L. | Kleber: 5 mm | Re.R. | Kleber: 5 mm |

| | | | |
|--|------------|------------|----------------|
| Assistance equipment | | | |
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 2767,60 |
| Wing R R, Dent(s), PDR - Paintless dent repair | | | 63,00 |



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

302,16



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

417,84



Roof pillar L, Hail damage, PDR - Hail

25,00



Wing F L, Scratch(es), LI - Repair and paint (complete)

264,21



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Dent(s), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

302,16



Roof pillar R, Hail damage, PDR - Hail

25,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

264,21



Bonnet, Hail damage, PDR - Hail

175,00



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

482,02



Roof, Hail damage, PDR - Hail

125,00



Rearlight L, Crack, E - Replace

132,00

