


BMW 3: 1GJE571

Vinnumber:	WBA3K110X0F858761	Versionname:	3 TOURING 318dA 136PK Aut.
First Registrationdate:	21/02/2014	Fiscalpower:	
Expertise Mileage:	142964	Power Kw:	100
Bodytype:	Break	Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2501
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			0,00
Door F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Rear window, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing R L, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Bonnet, Bad repair, Acceptable			0,00



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Bad repair, Acceptable	0,00



Door R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	