



FORD TRANSIT: 1E0U188

Vinnumber:	WF05XXBDF5CL47562	Versionname:	
First Registrationdate:	8/02/2013	Fiscalpower:	
Expertise Mileage:	285447	Power Kw:	74
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	LCV82
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	6		
Number head rests:	6		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/70/15/104 MS Steel			
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------


Total cost ex VAT	2072,95
-------------------	----------------

Windscreen, Stone chip(s), E - Replace	395,40
--	---------------





Rearlight R , Broken, E - Replace 91,50



Window separation wall, Missing, Forfeit 50,00

No pictures to display

Wing R L, Dent(s), It - Spot repair 115,56



Sill outer R, Rust, LI - Repair and paint (complete) 232,88



Rearlight L, Crack, E - Replace 91,50



Bumper trim R, Scratch(es), Smart repair 110,64



Trunk door R R, Dent(s), LI - Repair and paint (complete) 250,00



Wing F L, Rust, It - Spot repair 115,56



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Wing R R, Rust, LI - Repair and paint (complete) 231,15



Ignition key, Missing, E - Replace

150,00

No pictures to display