



FIAT Doblo: 349BYX

| | | | |
|-------------------------|--------------------------|--------------|---------------------------|
| Vinnumber: | ZFA26300009040731 | Versionname: | DOBLO Dynamic 95PK |
| First Registrationdate: | 26/08/2010 | Fiscalpower: | |
| Expertise Mileage: | 25445 | Power Kw: | 70 |
| Bodytype: | | Body color: | White |
| Gearbox: | MAN 5 VIT | Paint type: | Opaque |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Petrol | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3604 |
| Number of doors: | 6 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | | |
|-------------------------|-----------------------------|-----------------|----------------------|
| Radio CD | | Luggage cover | |
| Windows electric F | | Type of Tow bar | Tow bar fixed |
| Type of headlighting | Headlighting Halogen | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | No climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Tires wear profile | OK | Battery functioning | Yes |
| Idle position | OK | Power steering | Yes |
| Engine startingtime | OK | Sound engine | OK |
| Exhaust gass | OK | Clutch test | OK |
| Handbrake | OK | Wiper fluid level | OK |
| | | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------|-------|-----------------------|-------|-----------------------|
| 195/60/16/99 H Steel | | | | |
| Summer tyres: | Fr.L. | Goodyear: 5 mm | Fr.R. | Goodyear: 5 mm |
| | Re.L. | Goodyear: 5 mm | Re.R. | Goodyear: 5 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|---|---------|
| Total cost ex VAT | 1029,59 |
| Bumper F, Scratch(es), LI - Repair and paint (complete) | 158,85 |



| | |
|--|------|
| Boot carpet, Chemical polution, Acceptable | 0,00 |
|--|------|



Fuel cap cover, Broken, Le - Replace and paint

110,00



Door frame R R, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R L, Scratch(es), Acceptable

0,00

No pictures to display

Interior, Dirty, Acceptable

0,00



Door F R, Dent(s), Acceptable

0,00

No pictures to display

Mirror side blinker R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

158,85



Ignition key, Broken, E - Replace

150,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

286,76



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

165,13



Wheel cover F R, Scratch(es), Acceptable

0,00

No pictures to display

No pictures to display

Wheel cover F L, Scratch(es), Acceptable

0,00

No pictures to display