



BMW 4: 1FXW382			
Vinnumber:	WBA3P11030F781068	Versionname:	4 COU 420d 163PK
First Registrationdate:	2/12/2013	Fiscalpower:	
Expertise Mileage:	91424	Power Kw:	120
Bodytype:	Coupé	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2522
Number of doors:	2		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	225/40/19/89 Y LightMetal		
	Fr.L.	Fr.R.	Bridgestone: 6 mm
	Re.L.	Re.R.	Bridgestone: 4 mm

Assistance equipment	
Total cost ex VAT	2523,66
Bumper F, Dent(s) and scratch(es), Le - Replace and paint	862,80





Roof, Scratch(es), 67 - Polish 0,00

No pictures to display


Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Scratch(es), 67 - Polish 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Backrest cover F R, Worn, Acceptable 0,00





Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim R L polished, Scratch(es), Acceptable

0,00

No pictures to display