



**FORD Transit 330M: 521BUG**

Vinnumber:	<b>WF0XXXTFXAJ38639</b>	Versionname:	<b>TRANSIT B/F 330M MWB Silverl.DPF 140PK</b>
First Registrationdate:	<b>28/06/2010</b>	Fiscalpower:	
Expertise Mileage:	<b>165854</b>	Power Kw:	<b>103</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>TRU12</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>2</b>		
Number head rests:	<b>2</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Radio CD	Central consol F
GPS storage	<b>SD</b>
GPS storage	
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/75/16/92 MS Steel</b>			
Winter tyres:	Fr.L.	<b>Semperit: 5 mm</b>	Fr.R.	<b>Semperit: 5 mm</b>
	Re.L.	<b>Semperit: 6 mm</b>	Re.R.	<b>Semperit: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>1902,52</b>
Bumper R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Spare wheel compartment lining R R, Scratch(es), Forfeit			<b>150,00</b>



Spare wheel compartment lining R L, Dent(s), Forfeit

200,00



Rearlight L, Crack, E - Replace

91,50



Rearview mirror R complete, Broken, E - Replace

138,00



Registration Document, Missing, E - Replace

150,00

*No pictures to display*

Door R R, Dent(s), LI - Repair and paint (complete)

262,76



Sill outer L, Rust, LI - Repair and paint (complete)

232,88



Wing R R, Dent(s), Acceptable

0,00

*No pictures to display*

Trunk door panel L, Hole, E - Replace

5,00



Certificate Of Conformity, Missing, E - Replace

150,00

*No pictures to display*

Roof, Rust, LI - Repair and paint (complete)

361,13



Aerial, Damaged, E - Replace

11,25



Rear bulkhead lining, Scratch(es), Forfeit

150,00

