



MINI 5D: 1SSX172

Vinnumber:	WMWXT310902B52448	Versionname:	Cooper D (85 kW)
First Registrationdate:	6/07/2017	Fiscalpower:	
Expertise Mileage:	55282	Power Kw:	85
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2117
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	175/65/15/84 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	496,36
Door R L, Scratch(es), It - Spot repair	115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Protection plate M, Deformed / Strained, E - Replace

74,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Bodywork, Not original part, Acceptable

0,00

No pictures to display