



MERCEDES GLA: 1KFC203

Vinnumber:	WDC1569081J116818	Versionname:	2.1 GLA 200 CDI
First Registrationdate:	20/04/2015	Fiscalpower:	
Expertise Mileage:	85212	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2330
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	215/60/17/96 H Steel			
	Fr.L.	Uniroyal: 2 mm	Fr.R.	Uniroyal: 2 mm
	Re.L.	Uniroyal: 8 mm	Re.R.	Uniroyal: 8 mm


Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1144,84

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 362,02





Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Wheel cover R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), Smart repair

110,64



Wheel cover F L, Scratch(es), E - Replace

36,00



Wheel cover F R, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete)

382,02



Wheel cover R L, Scratch(es), Acceptable

0,00

No pictures to display