


OPEL Astra: 1GRP481

| | | | |
|------------------------------------|--------------------------|--------------|---|
| Vinnnummer: | WOLPD8EW8E8043779 | Versionname: | ASTRA BRE ecoFLEX Business 110PK |
| First Registrationdate: | 9/04/2014 | Fiscalpower: | |
| Expertise Mileage: | 130469 | Power Kw: | 81 |
| Bodytype: | Break | Body color: | Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1215 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|-------------------------------|--------------------------|
| Radio CD | Central consol F | |
| Windows electric F | Luggage cover | |
| Cruise Control | Rear parking sensors | |
| Steering wheel multifunctional | Type of Tow bar | Tow bar removable |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining semi-leather | |
| Type of climate control | Manual climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
| | 215/60/16/99 H Steel | | | |
| Winter tyres: | Fr.L. | Michelin: 6 mm | Fr.R. | Michelin: 6 mm |
| | Re.L. | Goodyear: 6 mm | Re.R. | Goodyear: 6 mm |

Assistance equipment

| | |
|-------------|------------|
| Spare wheel | Yes |
|-------------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 996,86 |
|-------------------|--------|

| | |
|--|------|
| Rearview mirror housing L, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|------------------------------------|------|
| Door R L, Scratch(es), 67 - Polish | 0,00 |
|------------------------------------|------|

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer L, Dent(s), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Dent(s), PDR - Paintless dent repair 63,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Rear window, Scratch(es), E - Replace 0,00



Wing R L, Scratch(es), 67 - Polish 0,00

No pictures to display

Window R R door, Scratch(es), Acceptable 0,00

No pictures to display