


**FORD S-MAX: 1NH705**

|                                    |                          |              |  |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber:                         | <b>WF0JXXWPCJG854493</b> | Versionname: | <b>2.0 TDCI 132KW S/S BUSINESS ED+</b> |
| First Registrationdate:            | <b>1/03/2016</b>         | Fiscalpower: |  |
| Expertise Mileage:                 | <b>109607</b>            | Power Kw:    | <b>132</b>                             |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                            |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                         |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                       |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                              |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>2230</b>                            |
| Battery functioning:               | <b>Yes</b>               |              |  |
| Number of doors:                   | <b>5</b>                 |              |  |
| Number of seats:                   | <b>7</b>                 |              |  |
| Number head rests:                 | <b>7</b>                 |              |  |
| Rims summer:                       | <b>Aluminium</b>         |              |  |
| Category:                          | <b>Passenger Car</b>     |              |  |
| Oil level:                         | <b>OK</b>                |              |  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |  |

**Options**

|                                |                                  |                       |                          |
|--------------------------------|----------------------------------|-----------------------|--------------------------|
| Radio CD                       |                                  | Central consol F      |                          |
| GPS storage                    |                                  | Luggage cover         |                          |
| GPS storage                    | <b>HD</b>                        | Front parking sensors |                          |
| Windows electric F             |                                  | Rear parking sensors  |                          |
| Windows electric R             |                                  | Type of Tow bar       | <b>Tow bar removable</b> |
| Cruise Control                 |                                  |                       |                          |
| Steering wheel multifunctional |                                  |                       |                          |
| Seats F heated                 |                                  |                       |                          |
| Type of headlighting           | <b>Headlighting LED</b>          |                       |                          |
| Type of GPS                    | <b>GPS big screen color</b>      |                       |                          |
| Type of Lining                 | <b>Lining artificial leather</b> |                       |                          |
| Type of climate control        | <b>Autom climate control</b>     |                       |                          |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                   |                       |       |                       |
|---------------|-----------------------------------|-----------------------|-------|-----------------------|
|               | <b>235/55/17/92 MS LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                             | <b>Michelin: 5 mm</b> | Fr.R. | <b>Michelin: 5 mm</b> |
|               | Re.L.                             | <b>Michelin: 6 mm</b> | Re.R. | <b>Michelin: 6 mm</b> |

**Assistance equipment**

|                       |            |      |            |
|-----------------------|------------|------|------------|
| Spare wheel           | <b>Yes</b> | Jack | <b>Yes</b> |
| Emergency spare wheel | <b>Yes</b> |      |            |

|  |        |
|--|--------|
| Total cost ex VAT  | 779,21 |
| Bumper R, Scratch(es), Acceptable                            | 0,00   |
| <i>No pictures to display</i>                                |        |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00  |



Wing F L, Scratch(es), LI - Repair and paint (complete)

264,21



Wing R L, Repaired, Acceptable

0,00



Rear window, Scratch(es), E - Replace

420,00

