



**MERCEDES GLA 200: 1HTX019**

Vinnumber:	<b>WDC1569081J060854</b>	Versionname:	<b>CDI</b>
First Registrationdate:	<b>1/10/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>57520</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>A7 IN 209 DAYS</b>	Parking lot:	<b>2732</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>1</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining artificial leather</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/60/17/96 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 6 mm</b>	Fr.R.	<b>Continental: 6 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

<b>Total cost ex VAT</b>	<b>2633,69</b>
--------------------------	----------------

<b>Door F L, Scratch(es), It - Spot repair</b>	<b>115,56</b>
--	---------------



Wing trim R R, Scratch(es), E - Replace

96,00



Outer valance R, Scratch(es), E - Replace

140,49



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

360,21



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

302,16



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Interior, No damage, No repair

0,00



Door R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing trim R L, Scratch(es), E - Replace

96,00





Wing moulding F L, Deformed / Strained, E - Replace

17,28



Interior, Dirty, Cleaning

50,00



Bumper R, Dent(s) and scratch(es), Le - Replace and paint

766,80



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper trim R, Dent(s) and scratch(es), E - Replace

190,42





Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Dent(s), Acceptable

0,00

Wing F R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	288,21
	
Bumper Trim F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	