


RENAULT Megane: 1EVN537

Vinnumber:	VF1KZ1A0748639741	Versionname:	MEGANE GT TomTom Edition 90PK
First Registrationdate:	1/04/2013	Fiscalpower:	
Expertise Mileage:	104953	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3303
Battery functioning:	No		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
GPS storage	SD
GPS storage	
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	No
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/92 MS Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			3824,87
Door catch R R, Missing, E - Replace			34,45



Wheel cover F L, Scratch(es), E - Replace

30,00



Wing F R, Dent(s), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Luggage space cover, Missing, E - Replace

240,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Rear window, Scratch(es), E - Replace

370,00



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete)

220,18



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R L, Dent(s) and scratch(es), Le - Replace and paint 1231,51



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) 290,08



Wheel cover R L, Broken, E - Replace 30,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35

