



**TOYOTA AYGO: 1PUU985**

Vinnumber:	<b>JTDKGNEC40N171566</b>	Versionname:	<b>1.0 VVT-I X-PLAY</b>
First Registrationdate:	<b>23/09/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>158533</b>	Power Kw:	<b>51</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2721</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Type of Tow bar	<b>No Tow bar</b>
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

Winter tyres:	<b>175/65/15/84 T Steel</b>			
	Fr.L.	<b>Uniroyal: 4 mm</b>	Fr.R.	<b>Uniroyal: 4 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>1976,49</b>
-------------------	----------------

Wheel cover F L, Scratch(es), E - Replace	<b>24,00</b>
---	--------------





Wheel cover F R, Missing, E - Replace 24,00



Luggage space cover, Missing, E - Replace 192,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 169,44



Internal Boot Lining L, Scratch(es), Smart repair 110,64



Interior, Dirty, Cleaning 50,00



Door R R, Scratch(es), 67 - Polish 0,00

No pictures to display


Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Wing F R, Deformed / Strained, Le - Replace and paint 448,01



Seat cover F L, Damaged, Smart repair 64,32



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 246,56



Maintenance book, Missing, E - Replace 0,00

No pictures to display

Wheel cover R L, Scratch(es), E - Replace 24,00



Ignition key, Missing, E - Replace 150,00

No pictures to display

Internal Boot Lining R, Scratch(es), Smart repair 110,64



Bumper F, Scratch(es), LI - Repair and paint (complete) 169,44



Wheel cover R R, Scratch(es), E - Replace 24,00

