



PORSCHE MACAN: 1K5E038

Vinnumber:	WP1ZZZ95ZGLB60729	Versionname:	3.0 V6 TD S 4WD (190 KW)
First Registrationdate:	22/06/2015	Fiscalpower:	
Expertise Mileage:	50360	Power Kw:	190
Bodytype:	SUV	Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2328
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Central consol F	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar fixed
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/60/18/103 V LightMetal				
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Total cost ex VAT	1647,12
Door F L, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Luggage space cover, Missing, E - Replace	288,00



Bonnet, Scratch(es), LI - Repair and paint (complete)

348,09



Bumper F, Dent(s) and scratch(es), Smart repair

110,64



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete)

264,21



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Tailgate, Scratch(es), 67 - Polish

0,00

No pictures to display