


**RENAULT Grand Scenic: 1GIL154**

|                                    |                          |              |  |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber:                         | <b>VF1JZ14M650343079</b> | Versionname: | <b>GRAND SCENIC Business 5pl.110PK</b> |
| First Registrationdate:            | <b>17/02/2014</b>        | Fiscalpower: |  |
| Expertise Mileage:                 | <b>130623</b>            | Power Kw:    | <b>81</b>                              |
| Bodytype:                          |                          | Body color:  | <b>White</b>                           |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                         |
| Transmission:                      |                          | Rims summer: | <b>Steel</b>                           |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                              |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3425</b>                            |
| Number of doors:                   | <b>5</b>                 |              |  |
| Number of seats:                   | <b>5</b>                 |              |  |
| Number head rests:                 | <b>5</b>                 |              |  |
| Rims summer:                       | <b>Steel</b>             |              |  |
| Category:                          | <b>Passenger Car</b>     |              |  |
| Oil level:                         | <b>OK</b>                |              |  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |  |

**Options**

|                                |                              |                      |
|--------------------------------|------------------------------|----------------------|
| Radio CD                       | Central consol F             |                      |
| Windows electric F             | Luggage cover                |                      |
| Windows electric R             | Front parking sensors        |                      |
| Cruise Control                 | Rear parking sensors         |                      |
| Steering wheel multifunctional | Type of Tow bar              | <b>Tow bar fixed</b> |
| Radio multimedia               |                              |                      |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |
| Type of Lining                 | <b>Lining fabrics</b>        |                      |
| Type of climate control        | <b>Autom climate control</b> |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                             |                       |       |                       |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
|               | <b>205/60/16/96 H Steel</b> |                       |       |                       |
| Winter tyres: | Fr.L.                       | <b>Michelin: 6 mm</b> | Fr.R. | <b>Michelin: 6 mm</b> |
|               | Re.L.                       | <b>Michelin: 5 mm</b> | Re.R. | <b>Michelin: 5 mm</b> |

**Assistance equipment**

|             |            |      |            |
|-------------|------------|------|------------|
| Spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-------------|------------|------|------------|

|   |               |
|---|---------------|
| Total cost ex VAT                                       | <b>842,16</b> |
| Windscreen, Repaired, Acceptable                        | <b>0,00</b>   |
| <i>No pictures to display</i>                           |               |
| Rearview mirror housing L, Scratch(es), Acceptable      | <b>0,00</b>   |
| <i>No pictures to display</i>                           |               |
| Wheel cover F R, Scratch(es), Acceptable                | <b>0,00</b>   |
| <i>No pictures to display</i>                           |               |
| Bumper R, Scratch(es), LI - Repair and paint (complete) | <b>211,80</b> |



Luggage space cover, Deformed / Strained, E - Replace 240,00



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete) 115,56



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), PDR - Paintless dent repair 63,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Roof pillar R, Scratch(es), Acceptable 0,00

No pictures to display