



VOLVO XC60: 1FRN757

Vinnumber:	YV1DZ31A1E2539587	Versionname:	XC60 D3 Kinetic 136PK
First Registrationdate:	2/10/2013	Fiscalpower:	
Expertise Mileage:	89905	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1331
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/65/17/104 MS LightMetal				
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Total cost ex VAT	524,64
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Floor covering F L, Hole, E - Replace	264,00



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Rearview mirror basis L, Scratch(es), Smart repair	110,64
----------------------------------------------------	--------



Interior, Dirty, Cleaning	0,00
---------------------------	------

