



**VOLVO V70: 1JFS441**

Vinnumber:	<b>YV1BW31A1F1326859</b>	Versionname:	<b>V70 D3 Polar 136PK</b>
First Registrationdate:	<b>4/12/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>105349</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3503</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar removable</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining artificial leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

Winter tyres:	<b>225/50/17/92 MS LightMetal</b>			
	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT 2168,79

Windscreen, Stone chip(s), Windscreen repair 58,80



Wing R L, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper trim R, Dent(s) and scratch(es), Smart repair 110,64



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Dent(s) and scratch(es), Le - Replace and paint 651,00



Rearlight R , Crack, E - Replace 114,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Dent(s), LI - Repair and paint (complete) 318,35



Backrest cover F L, Damaged, Acceptable 0,00



Headlight R, Scratch(es), E - Replace 396,00

