



AUDI A4: 1KAT982

Vinnumber:	WAUZZZ8K3FN034546	Versionname:	2.0 TDI ULTRA 100KW
First Registrationdate:	20/03/2015	Fiscalpower:	
Expertise Mileage:	84046	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2722
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	DVD	Rear parking sensors	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	864,41
-------------------	---------------

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 366,35



Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,50



Bumper R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Outer door handle F L, Scratch(es), LI - Repair and paint (complete) 115,56

