


BMW 3: 1FWI850

Vinnumber:	WBA3K11090F828246	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	18/11/2013	Fiscalpower:	
Expertise Mileage:	180702	Power Kw:	100
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4528
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric	
Windows electric F	Panoramic roof	
Windows electric R	Central consol F	
Cruise Control	Luggage cover	
Steering wheel multifunctional	Rear parking sensors	
Seats F heated	Type of Tow bar	Tow bar fixed
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			396,68
Door R L, Dent(s) and scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00



Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68

