


FORD S Max: 1HDC698

Vinnumber:	WF05XXGBWSET45216	Versionname:	S-MAX Trend Style St/St DPF 115PK
First Registrationdate:	23/06/2014	Fiscalpower:	
Expertise Mileage:	71332	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4602
Maintenance:	GEEN MELDING		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/99 H LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------








Total cost ex VAT	851,24
-------------------	--------

Tailgate, Chemical polution, Acceptable	0,00
---	------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door trim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Door R R, Repaired, No repair	0,00
<i>No pictures to display</i>	
Ignition key, Missing, E - Replace	150,00
	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel bolt cover R R, Missing, E - Replace	5,00
	
Mirror side blinker R, Scratch(es), E - Replace	31,20
	
Wing R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wheel bolt cover R L, Missing, E - Replace	25,00
	
Wing R R, Repaired, No repair	0,00
<i>No pictures to display</i>	
Mirror side blinker L, Scratch(es), E - Replace	31,20
	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel bolt cover F R, Missing, E - Replace	15,00
	
Wheel bolt cover F L, Missing, E - Replace	15,00



Wing F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), E - Replace

483,84

