



**CITROEN C4 Picasso: 1GNU636**

Vinnumber:	<b>VF73A9HC8DJ802778</b>	Versionname:	<b>GR.C4 PICASSO Business GPS 115PK</b>
First Registrationdate:	<b>20/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>160582</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>4732</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/16/92 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>Firestone: 6 mm</b>	Fr.R.	<b>Firestone: 6 mm</b>
	Re.L.	<b>Firestone: 8 mm</b>	Re.R.	<b>Firestone: 8 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>2078,15</b>
Door F R, Dent(s), PDR - Paintless dent repair			<b>63,00</b>



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Headlight L, Broken, E - Replace 396,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bad repair, LI - Repair and paint (complete) 452,20



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 414,35



Maintenance, Maintenance, P - Check 0,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Foglight R, Broken, E - Replace 138,00





Bumper R, Scratch(es), LI - Repair and paint (complete)

259,80



Rearview mirror housing L, Scratch(es), Acceptable

0,00

*No pictures to display*

Mats, Worn, Acceptable

0,00

*No pictures to display*

Bonnet, Stone chip(s), Acceptable

0,00

*No pictures to display*

Windscreen, Stone chip(s), E - Replace

0,00



Alloy rim F L, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper F, Scratch(es), LI - Repair and paint (complete)

259,80

