



FORD GALAXY: 1NPT618

Vinnumber:	WF0KXXWPCKFY77062	Versionname:	2.0 TDCI 110KW S/S BUSINESS EDITION+
First Registrationdate:	4/04/2016	Fiscalpower:	
Expertise Mileage:	61918	Power Kw:	110
Bodytype:		Body color:	Green
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4730
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	SD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/55/17/103 H-MS LightMetal				
Summer tyres:	Fr.L.	Goodyear: 2 mm	Fr.R.	Goodyear: 2 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	3258,08
-------------------	----------------

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

<i>No pictures to display</i>	
-------------------------------	--

Luggage space cover, Missing, E - Replace	288,00
---	---------------



Spoiler R, Deformed / Strained, E - Replace

166,60



Door R L, Deformed / Strained, Forfeit

0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

430,02



Windscreen, Scratch(es), E - Replace

560,64



Bumper R, Dent(s) and scratch(es), Le - Replace and paint

766,80



Rear window, Scratch(es), E - Replace

420,00



Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Outer valance R, Tear, Le - Replace and paint

626,02



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display