



FORD GRAND TOURNEO CONNECT: 1RBC142

Vinnumber:	WFOUXXWPGUGY79025	Versionname:	1.5 TDCI 90KW TITANIUM
First Registrationdate:	2/11/2016	Fiscalpower:	
Expertise Mileage:	68650	Power Kw:	88
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4606
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Panoramic roof	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Vredestein: 3 mm	Fr.R.	Vredestein: 3 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1562,27
Door F R, Scratch(es), LI - Repair and paint (complete)	238,76



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)

238,76



Bumper R, Scratch(es), LI - Repair and paint (complete)

158,85



Tailgate, Dent(s), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)

231,15



Roof pillar R, Dent(s), Acceptable

0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete)

165,13



Trunk lid covering R, Scratch(es), Smart repair

110,64



Roof pillar L, Dent(s), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

158,85





Wing F R, Scratch(es), LI - Repair and paint (complete)

165,13

