



**MERCEDES Sprinter 300: 1HFY003**

|                                    |                          |              |  |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber:                         | <b>WDB90663315946286</b> | Versionname: | <b>SPRINTER 316 B/F MWB A2H2 163PK</b> |
| First Registrationdate:            | <b>10/07/2014</b>        | Fiscalpower: |  |
| Expertise Mileage:                 | <b>200248</b>            | Power Kw:    | <b>120</b>                             |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                            |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                         |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Steel</b>                           |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                              |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>LCV30</b>                           |
| Battery functioning:               | <b>Yes</b>               |              |  |
| Number of doors:                   | <b>5</b>                 |              |  |
| Number of seats:                   | <b>3</b>                 |              |  |
| Number head rests:                 | <b>3</b>                 |              |  |
| Rims summer:                       | <b>Steel</b>             |              |  |
| Category:                          | <b>VS</b>                |              |  |
| Oil level:                         | <b>OK</b>                |              |  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |  |

**Options**

|                         |                               |                       |                      |
|-------------------------|-------------------------------|-----------------------|----------------------|
| Windows electric F      |                               | Central consol F      |                      |
| Radio multimedia        |                               | Front parking sensors |                      |
| Type of headlighting    | <b>Headlighting Halogen</b>   | Rear parking sensors  |                      |
| Type of GPS             | <b>No GPS</b>                 | Type of Tow bar       | <b>Tow bar fixed</b> |
| Type of Lining          | <b>Lining fabrics</b>         |                       |                      |
| Type of climate control | <b>Manual climate control</b> |                       |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                              |                         |       |                         |
|---------------|------------------------------|-------------------------|-------|-------------------------|
|               | <b>235/65/16/113 R Steel</b> |                         |       |                         |
| Winter tyres: | Fr.L.                        | <b>Uniroyal: 5,3 mm</b> | Fr.R. | <b>Uniroyal: 5,4 mm</b> |
|               | Re.L.                        | <b>Uniroyal: 5,5 mm</b> | Re.R. | <b>Uniroyal: 5,3 mm</b> |

**Assistance equipment**

|             |            |      |            |
|-------------|------------|------|------------|
| Spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-------------|------------|------|------------|

|                   |                |
|-------------------|----------------|
| Total cost ex VAT | <b>2172,93</b> |
|-------------------|----------------|

|   |               |
|---|---------------|
| Wing R L, Dent(s), LI - Repair and paint (complete) | <b>369,84</b> |
|---|---------------|





Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Mirror side blinker R, Broken, E - Replace 31,20



Bonnet, Scratch(es), LI - Repair and paint (complete) 348,09



Rearlight R, Broken, E - Replace 132,00



Door F L, Dent(s), It - Spot repair 115,56



Wing R R, Scratch(es), LI - Repair and paint (complete) 369,84



Mirror side blinker L, Broken, E - Replace 31,20



Bodywork, Not original part, Remove lettering 130,00



Bumper corner R L, Dent(s), E - Replace 94,20



Trunk door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 356,00



Interior, Dirty, Cleaning 130,00



Reflector, Crack, E - Replace

15,00



Trunk door panel L, Missing, E - Replace

50,00

