



OPEL Insignia: 1GFQ541

Vinnumber:	WOLGM8ER9E1064997	Versionname:	INSIGNIA BRE ecoFLEX Edition 120PK
First Registrationdate:	27/01/2014	Fiscalpower:	
Expertise Mileage:	130810	Power Kw:	88
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2425
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/95 H LightMetal				
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			544,00
Bumper grille, Broken, E - Replace			32,40



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Wing F R, Dent(s), PDR - Paintless dent repair

63,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Alloy Rims (all), Rust, Acceptable

0,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Bad repair, Acceptable

0,00



Seat cover R, Stain, Cleaning

25,00



Wing R L, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80



Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner F R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	