


PEUGEOT 508 SW: 1LNy609

Vinnumber:	VF38EAHSMFL045062	Versionname:	2.0 BLUEHDI 100KW S/S ACTIVE
First Registrationdate:	2/11/2015	Fiscalpower:	
Expertise Mileage:	186395	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4628
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Seats electric F L	
GPS storage	HD	Seats electric F R	
Windows electric F		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar fixed
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H LightMetal			
Winter tyres:	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1215,98
Wing R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Dent(s), PDR - Paintless dent repair	63,00



Foglight R, Crack, E - Replace

138,00



Wing F L, Dent(s), LI - Repair and paint (complete)

220,18



Door F L, Dent(s), PDR - Paintless dent repair

63,00



Door R R, Dent(s), Acceptable

0,00

No pictures to display

Bumper F, Dent(s), LI - Repair and paint (complete)

211,80



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Wing F R, Dent(s), Acceptable

0,00

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80

