



VOLVO V60: 1PTV377

Vinnumber:	YV1FW74C1H1332618	Versionname:	2.0 D2 VOLVO OCEAN RACE
First Registrationdate:	16/09/2016	Fiscalpower:	
Expertise Mileage:	192034	Power Kw:	88
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4814
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/40/18/95 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1781,00
-------------------	---------

Door F R, Chemical polution, Acceptable	0,00
---	------

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	259,80
---	--------



Door F L, Repaired, Acceptable 0,00

No pictures to display

Internal Boot Lining L, Scratch(es), E - Replace 99,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper grille, Broken, E - Replace 32,40



Sill outer R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 283,80



Door panel R R, Tear, E - Replace 114,00



Floor covering F L, Tear, E - Replace 252,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover R, Tear, E - Replace 360,00

