



VOLVO XC60: 1EWM308

Vinnumber:	YV1DZ8756D2453827	Versionname:	XC60 D4 AWD Kinetic Geartr.163PK Aut.
First Registrationdate:	8/04/2013	Fiscalpower:	
Expertise Mileage:	112062	Power Kw:	120
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4323
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/65/17/104 H LightMetal				
Winter tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2410,79
Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	264,21



Luggage space cover, Deformed / Strained, Forfeit 9,60



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 430,02



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Deformed / Strained, Le - Replace and paint 862,80





Spoiler R, Scratch(es), E - Replace

198,00



Ignition key, Missing, E - Replace

150,00



Boot carpet, Stain, Cleaning

25,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper spoiler F, Deformed / Strained, E - Replace

122,00

