


**OPEL Insignia: 1FTG395**

|                                    |                          |              |   |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber:                         | <b>WOLGT6ER3E1019805</b> | Versionname: | <b>INSIGNIA BER ecoFLEX Cosmo 120PK</b> |
| First Registrationdate:            | <b>17/10/2013</b>        | Fiscalpower: | <b>88</b>                               |
| Expertise Mileage:                 | <b>130640</b>            | Power Kw:    | <b>88</b>                               |
| Bodytype:                          |                          | Body color:  | <b>Black</b>                            |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metallic</b>                         |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                        |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                               |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>3709</b>                             |
| Battery functioning:               | <b>Yes</b>               |              |   |
| Number of doors:                   | <b>5</b>                 |              |   |
| Number of seats:                   | <b>5</b>                 |              |   |
| Number head rests:                 | <b>5</b>                 |              |   |
| Rims summer:                       | <b>Aluminium</b>         |              |   |
| Category:                          | <b>Passenger Car</b>     |              |   |
| Oil level:                         | <b>OK</b>                |              |   |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |   |

**Options**

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD                       |                              | Central consol F      |                   |
| GPS storage                    | <b>HD</b>                    | Luggage cover         |                   |
| GPS storage                    |                              | Front parking sensors |                   |
| Windows electric F             |                              | Rear parking sensors  |                   |
| Windows electric R             |                              | Type of Tow bar       | <b>No Tow bar</b> |
| Cruise Control                 |                              |                       |                   |
| Steering wheel multifunctional |                              |                       |                   |
| Seats F heated                 |                              |                       |                   |
| Radio multimedia               |                              |                       |                   |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining leather</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                            |       |                            |
|----------------------------------|-------|----------------------------|-------|----------------------------|
| <b>225/55/17/97 W LightMetal</b> |       |                            |       |                            |
| Summer tyres:                    | Fr.L. | <b>Bridgestone: 4,4 mm</b> | Fr.R. | <b>Bridgestone: 4,6 mm</b> |
|                                  | Re.L. | <b>Kleber: 5,3 mm</b>      | Re.R. | <b>Kleber: 5,2 mm</b>      |

**Assistance equipment**

|                       |            |      |            |
|-----------------------|------------|------|------------|
| Emergency spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-----------------------|------------|------|------------|

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 245,00 |
|-------------------|--------|

|  |      |
|--|------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

|                                    |        |
|------------------------------------|--------|
| Ignition key, Missing, E - Replace | 150,00 |
|------------------------------------|--------|

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim R R, Scratch(es), Acceptable

0,00

*No pictures to display*

Door R L, Dent(s), Acceptable

0,00

*No pictures to display*

Wing R R, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper R, Scratch(es), Acceptable

0,00

*No pictures to display*