



MINI Mini: 1GJN016

Vinnumber:	WMWSW11010T464938	Versionname:	MINI One D 90PK DPF
First Registrationdate:	25/02/2014	Fiscalpower:	
Expertise Mileage:	92209	Power Kw:	66
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1314
Number of doors:	3		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


175/65/15/84 H LightMetal				
Summer tyres:	Fr.L.	Semperit: 7 mm	Fr.R.	Semperit: 7 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 2679,13

Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) 290,08



Bumper R, Scratch(es), Smart repair 110,64



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00




Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80





Roof, Scratch(es), LI - Repair and paint (complete)

481,50



Wing R R, Scratch(es), It - Spot repair

115,56




Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), Smart repair

110,64



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Floor covering F L, Dirty, Cleaning

25,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

