



PEUGEOT 508 SW: 1KJC442

Vinnumber:	VF38EBHXMFL017562	Versionname:	1.6 BLUEHDI S/S ACTIVE
First Registrationdate:	11/05/2015	Fiscalpower:	
Expertise Mileage:	123942	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4715
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Panoramic roof	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/95 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1553,26
-------------------	----------------

Seat cover F L, Scratch(es), Acceptable	0,00
---	-------------







No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

<i>No pictures to display</i>		
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door seal F R, Broken, E - Replace		54,00
		
Door F L, Deformed / Strained, Acceptable		0,00
<i>No pictures to display</i>		
Rearlight R , Waterinfiltration, Acceptable		0,00
		
Window R L door, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper F, Dent(s), It - Spot repair		115,56
<i>No pictures to display</i>		
Wing R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Moulding windscreen R, Damaged, E - Replace		54,00
		
Door F R, Scratch(es), LI - Repair and paint (complete)		318,35
		
Bonnet, Chemical polution, Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)		235,80
		
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)		308,20



Door seal R R, Broken, E - Replace 54,00



Bumper F, Scratch(es), Acceptable 0,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 318,35

