


OPEL ASTRA SPORTS TOURER: 1LHC895

| | | | |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber: | W0LPD8E6XF8077255 | Versionname: | 1.6 CDTI 81KW ECOFLEX S/S ULTIMATE EDITI |
| First Registrationdate: | 28/09/2015 | Fiscalpower: | |
| Expertise Mileage: | 179870 | Power Kw: | 81 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metallic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 3431 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 4 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|-------------------------------|----------------------|--|
| Radio CD | | Luggage cover | |
| GPS storage | HD | Rear parking sensors | |
| GPS storage | | | |
| Windows electric F | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Manual climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------|-------|-----------------------|-------|-----------------------|
| 215/60/16/92 H Steel | | | | |
| Summer tyres: | Fr.L. | Uniroyal: 5 mm | Fr.R. | Uniroyal: 5 mm |
| | Re.L. | Uniroyal: 6 mm | Re.R. | Uniroyal: 6 mm |

Assistance equipment

| | | | |
|--|------------|------------|----------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 1327,98 |
| Door F R, Dent(s), PDR - Paintless dent repair | | | 63,00 |



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Luggage space cover, Damaged, E - Replace 240,00



Wing R L, Chemical polution, 67 - Polish 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Wheel cover F L, Crack, E - Replace 30,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 481,50

