



AUDI A3 SPORTBACK: DM6283

Vinnumber:	WAUZZZ8V0GA064347	Versionname:	1.6 TDI ULTRA ATTRACTION SPORTBACK
First Registrationdate:	6/11/2015	Fiscalpower:	
Expertise Mileage:	85561	Power Kw:	81
Bodytype:	Berline	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3815
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Winter tyres:	Fr.L.	Fulda: 5 mm	Fr.R.	Fulda: 8 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1273,45
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Seat cover F R, Stain, Cleaning 25,00



Wing F R, Bad repair, Acceptable 0,00




Wing R R, Bad repair, Acceptable 0,00



Door R R, Bad repair, Acceptable 0,00



Bumper R, Deformed / Strained, LI - Repair and paint (complete) 211,80




Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Seat cover R, Stain, Cleaning 25,00



Roof pillar L, Bad repair, Acceptable 0,00



Door F L, Dent(s), LI - Repair and paint (complete)

318,35

