



VOLKSWAGEN GOLF VARIANT: 1KFC194

Vinnumber:	WVWZZZAUZFP617183	Versionname:	1.6 CR TDI 77KW BMT TRENDLINE
First Registrationdate:	20/04/2015	Fiscalpower:	
Expertise Mileage:	100785	Power Kw:	77
Bodytype:	Break	Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3433
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT		1811,58
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)		211,80



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door R L, Scratch(es), Acceptable 0,00

No pictures to display


Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20




Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Door R R, Scratch(es), Acceptable 0,00

No pictures to display