



<b>BMW 3: 1JFX109</b>			
Vinnumber:	<b>WBA3L11030K177328</b>	Versionname:	<b>3 TOURING 320d Eff.Dyn.Ed. 163PK</b>
First Registrationdate:	<b>6/12/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>130100</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Break</b>	Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4511</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>205/60/16/92 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>4940,50</b>
<b>Door R R, Dent(s) and scratch(es), Le - Replace and paint</b>	<b>946,92</b>



Wing R L, Dent(s), PDR - Paintless dent repair

63,00




Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Rear window, Scratch(es), E - Replace

370,00



Foglight R, Crack, E - Replace

138,00



Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68




Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

548,20



Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Door F R, Dent(s) and scratch(es), Le - Replace and paint

1082,52



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Sill outer L, Scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Hail damage, PDR - Hail

200,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

