



AUDI A3 SPORTBACK: 1KHJ943

| | | | |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber: | WAUZZZ8V3FA156728 | Versionname: | 1.6 TDI ULTRA ATTRACTION SPORTBACK |
| First Registrationdate: | 5/05/2015 | Fiscalpower: | |
| Expertise Mileage: | 61573 | Power Kw: | 81 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 1307 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | SD | Luggage cover | |
| GPS storage | | Rear parking sensors | |
| Windows electric F | | Type of Tow bar | No Tow bar |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| 205/55/16/91 H LightMetal | | | | |
| Winter tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

Assistance equipment

| | |
|------------|------------|
| Repair kit | Yes |
|------------|------------|

| | |
|---|---------------|
| Total cost ex VAT | 506,98 |
| Roof pillar L, Dent(s) and scratch(es), LI - Repair and paint (complete) | 220,18 |



| | |
|--|------|
| Rearview mirror housing R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|-----------------------------------|------|
| Wing R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|--|-------|
| Bodywork, Not original part, Sticker removal small | 75,00 |
|--|-------|



| | |
|---|--------|
| Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|

