



AUDI A6 AVANT: 1NR986

Vinnumber:	WAUZZZ4G9GN142558	Versionname:	2.0 TDI ULTRA 110KW S TRONIC
First Registrationdate:	7/04/2016	Fiscalpower:	
Expertise Mileage:	142157	Power Kw:	110
Bodytype:	Break	Body color:	Dark Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4219
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric	
Windows electric F	Central consol F	
Windows electric R	Luggage cover	
Cruise Control	Front parking sensors	
Steering wheel multifunctional	Rear parking sensors	
Seats F heated	Type of Tow bar	Tow bar fixed
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 H LightMetal				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1788,60
Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

264,21



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Door R R, Scratch(es), LI - Repair and paint (complete)

382,02



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

264,21



Wing R R, Scratch(es), LI - Repair and paint (complete)

369,84

