



BMW 3: HK4016

Vinnumber:	WBA3Y11060D449232	Versionname:	3 GRAN TURISMO 318d 143PK
First Registrationdate:	1/03/2016	Fiscalpower:	
Expertise Mileage:	188403	Power Kw:	105
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel		
Maintenance:	OK		
Maintenance:	IN 41000 KM		
Battery functioning:	No		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tires wear profile	OK	Battery functioning	No
Engine startingtime	NOT OK	Clutch test	OK
Handbrake	OK	Wiper fluid level	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1299,15
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Interior, Dirty, Acceptable

0,00



Bodywork, Accident, No repair

0,00

No pictures to display

Door R R, Dent(s), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Protection plate M, Hole, E - Replace

44,60



Tires, Not original part, Acceptable

0,00

No pictures to display

Door frame R L, Dent(s), It - Spot repair

115,56



Dashboard, Scratch(es), Smart repair

110,64



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Door R L, Scratch(es), Acceptable

0,00

No pictures to display