


BMW 3 GRAN TURISMO: 1KBJ329

Vinnumber:	WBA3Y11000GD87280	Versionname:	2.0 318D (100KW) GRAN TURISMO
First Registrationdate:	25/03/2015	Fiscalpower:	
Expertise Mileage:	85729	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	-900KM	Parking lot:	4325
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1476,83
-------------------	---------

Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing R R, Dent(s), PDR - Paintless dent repair

63,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Maintenance, Maintenance, Execute

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Backrest cover F L, Scratch(es), Smart repair

64,32



Rearview mirror R complete, Broken, Le - Replace and paint

283,00



Rocker panel inner R L, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Rearlight L, Broken, E - Replace

114,00



Rocker panel inner R R, Scratch(es), Acceptable

0,00

No pictures to display

Outer door handle F R, Scratch(es), LI - Repair and paint (complete)

115,56

