



**BMW 5: 1FKL058**

Vinnumber:	<b>WBA5J310X0D067102</b>	Versionname:	<b>5 TOURING 520dA 163PK Aut.</b>
First Registrationdate:	<b>26/07/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>170999</b>	Power Kw:	<b>120</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OVER 19000KM</b>	Parking lot:	<b>2111</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/55/17/101 V LightMetal</b>				
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>No</b>
------------	-----------	------------	-----------

Total cost ex VAT	2703,78
-------------------	---------

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Bumper R, Deformed / Strained, LI - Repair and paint (complete)	254,16
---	--------



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Door R R, Scratch(es), Acceptable

0,00



Roof, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror basis R, Scratch(es), Smart repair

110,64



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Trunk lid covering R, Scratch(es), Smart repair

110,64



Tyre repair kit, Missing, E - Replace

252,64



Wing R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Backrest cover F L, Broken, E - Replace

408,00




Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Ceiling, Stain, Cleaning

25,00



Door frame R R, Scratch(es), It - Spot repair

115,56



Alloy rim F L, Scratch(es), Acceptable

0,00

*No pictures to display*