


BMW 3: 1JJG017

Vinnumber:	WBA3D11050J855337	Versionname:	3 BER 318dA 136PK Aut.
First Registrationdate:	2/01/2015	Fiscalpower:	
Expertise Mileage:	174709	Power Kw:	100
Bodytype:		Body color	BLAUW
Gearbox:	Automatic	Body color	Dark Blue
Transmission:	Back	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Maintenance	12000 KM	Oil level	OK
Maintenance	OK	Parking lot	1123
Maintenance	1/01/2020		
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	No	Compressor	No
Number of charging cables (normal)	0	Runflat	No
Number of charging cables (rapid charge)	0		

Total cost ex VAT	75,00
Alloy rim F R, Scratch(es), Acceptable	0,00

No pictures to display

Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tires, Out of tolerance, P - Check	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Compressor, Missing, E - Replace	75,00
<i>No pictures to display</i>	
Door R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	