



**MERCEDES GLA: 1GWA286**

|                                   |                          |              |                          |
|-----------------------------------|--------------------------|--------------|--------------------------|
| Vinnumber:                        | <b>WDC1569081J016512</b> | Versionname: | <b>GLA 200 CDI 136PK</b> |
| First Registrationdate:           | <b>15/05/2014</b>        | Fiscalpower: |                          |
| Expertise Mileage:                | <b>82630</b>             | Power Kw:    | <b>100</b>               |
| Bodytype:                         |                          | Body color   | <b>Light Blue</b>        |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b>           |
| Transmission:                     |                          | Rims summer  | <b>Aluminium</b>         |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>4415</b>              |
| Number of doors                   | <b>5</b>                 |              |                          |
| Number of seats                   | <b>5</b>                 |              |                          |
| Number head rests                 | <b>5</b>                 |              |                          |
| Rims summer                       | <b>Aluminium</b>         |              |                          |
| Category                          | <b>Passenger Car</b>     |              |                          |
| Oil level                         | <b>OK</b>                |              |                          |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                          |

**Options**

|                                |                               |
|--------------------------------|-------------------------------|
| Radio CD                       | Central consol F              |
| Windows electric F             | Front parking sensors         |
| Windows electric R             | Rear parking sensors          |
| Steering wheel multifunctional | Type of Tow bar               |
| Seats F heated                 | <b>No Tow bar</b>             |
| Radio multimedia               |                               |
| Type of headlighting           | <b>Headlighting Xenon</b>     |
| Type of GPS                    | <b>GPS big screen color</b>   |
| Type of Lining                 | <b>Lining leather</b>         |
| Type of climate control        | <b>Manual climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>215/60/17/96 V LightMetal</b> |                          |       |                          |
| Summer tyres: | Fr.L.                            | <b>Michelin: 5 mm</b>    | Fr.R. | <b>Michelin: 5 mm</b>    |
|               | Re.L.                            | <b>Continental: 6 mm</b> | Re.R. | <b>Continental: 6 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|   |               |
|---|---------------|
| Total cost ex VAT   | <b>808,52</b> |
| Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) | <b>254,16</b> |





Roof, Dent(s), Acceptable

0,00

*No pictures to display*

Bumper R, Dent(s) and scratch(es), Smart repair

110,64



Wing F L, Deformed / Strained, Repair/replace (lump sum)

74,00



Door F R, Dent(s), Acceptable

0,00

*No pictures to display*

Rocker panel inner F L, Dent(s), LI - Repair and paint (complete)

115,56



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Door F L, Scratch(es), Acceptable

0,00

*No pictures to display*