


MAZDA CX-3: 1NLS620

Vinnumber:	JMZDK6WS610144807	Versionname:	1.5 SKYACTIV-D 77KW PLUG EDITION
First Registrationdate:	18/03/2016	Fiscalpower:	
Expertise Mileage:	167543	Power Kw:	77
Bodytype:	SUV	Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1522
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	Tow bar removable
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	215/60/16/99 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			513,90
Bumper grille F R, Broken, E - Replace			32,40



Roof, Dent(s) and scratch(es), LI - Repair and paint (complete)	481,50
---	--------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display