



CITROEN C3 Picasso: 1HBR410

Vinnumber:	VF7SH5FS8ET520310	Versionname:	C3 PICASSO Exclusive BMP 120PK Aut.
First Registrationdate:	12/06/2014	Fiscalpower:	
Expertise Mileage:	30059	Power Kw:	88
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3706
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/55/16/91 T LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes
-----------------------	------------

Total cost ex VAT	1037,18
-------------------	----------------

Wing R R, Scratch(es), LI - Repair and paint (complete)	0,00
---	-------------



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,68
---	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)

232,06



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

169,44



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Door F R, Dent(s), Acceptable

0,00

No pictures to display

Door moulding Lower R R, Scratch(es), E - Replace

96,00

