



VOLKSWAGEN Golf: 1GGT179

| | | | |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnumber: | WVWZZZAUZEP559311 | Versionname: | GOLF VAR Trendline 105PK |
| First Registrationdate: | 4/02/2014 | Fiscalpower: | |
| Expertise Mileage: | 57229 | Power Kw: | 77 |
| Bodytype: | Break | Body color: | Black |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2118 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | Type of Tow bar |
| Radio multimedia | No Tow bar |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |
| Adaptive cruise control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-------------------------|-------|-------------------------|
| 205/55/16/91 H LightMetal | | | | |
| Summer tyres: | Fr.L. | Vredestein: 7 mm | Fr.R. | Vredestein: 7 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | |
|-----------------------|------------|
| Emergency spare wheel | Yes |
|-----------------------|------------|


| | |
|---|---------|
| Total cost ex VAT | 1344,30 |
| Bumper R, Deformed / Strained, Le - Replace and paint | 651,00 |



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Dent(s), Acceptable 0,00

No pictures to display