



## VOLVO V70: 1KJY258

|                                    |                          |              |                                  |
|------------------------------------|--------------------------|--------------|----------------------------------|
| Vinnumber:                         | <b>VV1BW73C1F1336276</b> | Versionname: | <b>2.0 D4 133KW POLAR LUXURY</b> |
| First Registrationdate:            | <b>18/05/2015</b>        | Fiscalpower: |                                  |
| Expertise Mileage:                 | <b>143288</b>            | Power Kw:    | <b>133</b>                       |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Silver</b>                    |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metallic</b>                  |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                 |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                        |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3201</b>                      |
| Number of doors:                   | <b>5</b>                 |              |                                  |
| Number of seats:                   | <b>5</b>                 |              |                                  |
| Number head rests:                 | <b>5</b>                 |              |                                  |
| Rims summer:                       | <b>Aluminium</b>         |              |                                  |
| Category:                          | <b>Passenger Car</b>     |              |                                  |
| Oil level:                         | <b>OK</b>                |              |                                  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                  |

## Options

|                                |                              |                          |
|--------------------------------|------------------------------|--------------------------|
| Radio CD                       | Sun Roof electric            |                          |
| Windows electric F             | Central consol F             |                          |
| Windows electric R             | Luggage cover                |                          |
| Cruise Control                 | Front parking sensors        |                          |
| Steering wheel multifunctional | Rear parking sensors         |                          |
| Seats F heated                 | Type of Tow bar              | <b>Tow bar removable</b> |
| Radio multimedia               |                              |                          |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                          |
| Type of GPS                    | <b>GPS big screen color</b>  |                          |
| Type of Lining                 | <b>Lining leather</b>        |                          |
| Type of climate control        | <b>Autom climate control</b> |                          |

## Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

## Degree of wear

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>225/50/17/98 H LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                            | <b>Bridgestone: 5 mm</b> | Fr.R. | <b>Bridgestone: 5 mm</b> |
|               | Re.L.                            | <b>Bridgestone: 5 mm</b> | Re.R. | <b>Bridgestone: 5 mm</b> |

## Assistance equipment

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |


|  |               |
|--|---------------|
| Total cost ex VAT  | <b>682,09</b> |
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | <b>95,00</b>  |



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Dent(s), LI - Repair and paint (complete) 492,09



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display