



MERCEDES Sprinter 300: 1HJK388

Vinnumber:	WDB90663315949291	Versionname:	SPRINTER 316 B/F MWB A2H2 163PK
First Registrationdate:	1/08/2014	Fiscalpower:	
Expertise Mileage:	140822	Power Kw:	120
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	LCV23
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	VS		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar fixed
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/65/16/113 R Steel				
Winter tyres:	Fr.L.	Michelin: 5,3 mm	Fr.R.	Michelin: 5,2 mm
	Re.L.	Michelin: 3,9 mm	Re.R.	Michelin: 3,8 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1592,08
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)			231,15



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	231,15
--	---------------



Mirror side blinker L, Crack, E - Replace

28,50



Sliding door R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Sliding door R, Deformed / Strained, Le - Replace and paint

200,50



Ignition key, Missing, E - Replace

150,00

No pictures to display

Bodywork, Not original part, Remove lettering

130,00



Door F L, Dent(s), LI - Repair and paint (complete)

238,76

