



FORD FIESTA: 1UMM265

Vinnumber:	WF0JXXGAHJJ02943	Versionname:	
First Registrationdate:	14/06/2018	Fiscalpower:	
Expertise Mileage:	27572	Power Kw:	62
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1213
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/55/16/87 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1390,34
Bonnet, Chemical polution, 67 - Polish	50,00





Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

169,44



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,68



Door R L, Dent(s), PDR - Paintless dent repair

63,00



Tailgate, Scratch(es), LI - Repair and paint (complete)

241,34



Sill trim R R, Scratch(es), Smart repair

110,64



Wing R R, Scratch(es), LI - Repair and paint (complete)

246,56



Door F R, Scratch(es), LI - Repair and paint (complete)

254,68

