



VOLKSWAGEN Polo: 1EVN487

Vinnumber:	WVWZZZ6RZDY234015	Versionname:	POLO Comfortline DPF 75PK
First Registrationdate:	1/04/2013	Fiscalpower:	
Expertise Mileage:	161437	Power Kw:	55
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4506
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Luggage cover	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	185/60/15/88 H Steel			
Summer tyres:	Fr.L.	Firestone: 4 mm	Fr.R.	Firestone: 4 mm
	Re.L.	Firestone: 4 mm	Re.R.	Firestone: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	256,06
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Chemical pollution, LI - Repair and paint (complete)	232,06



Windscreen, Stone chip(s), Windscreen repair 0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 24,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display